



UPDATE TO TSB 72 REGARDING PART NUMBER TUNI230	TSB #:	77
	Date:	24/5/2013
Initial Once Read:		

Adair can no longer source the automatic high side extended charging coupler as described in Technical Bulletin number 72, January 2013.

Instead, we can offer an equally well designed high side extended charge port coupler, in manually operated form. The bottom section of the coupler has a sleeve which must be lifted upwards when connecting (and disconnecting) the coupler from the concealed high side charge port. The red knurled knob on the top is turned clockwise to push the pin of the schrader valve open. Then you can carry out A/C servicing through the high side charge port.

With this **NEW** coupler the benefits are;

- ◇ Full brass construction
- ◇ Can be fitted to 1/2" acme (R134a) or 1/4" MF (R12 type) A/C service hoses



Previous Automatic Version



Adair part number TUNI230 has been replaced by this Manually Operated High Side Charging Coupler



New coupler shown fitted to the concealed high side charge port of a 2008 MA Ford Mondeo